



Taiwan Labeling Standards for Washed Down & Feather

Source: CNS2119 N 1034

Testing Methods

Taiwan Standard currently uses methods outlined in CNS2119 N 1034 guidelines.

Cleanliness Requirements

Turbidity.....> 300mm

Specie (Goose or Duck)

Products can be labeled by specie if 90% of the plumage is of that specie.

Moisture

The Moisture value should be less than 13%.

Odor

Must not have a distinct odor smell.

Composition statement	Minimum required down cluster	Maximum down fiber	Maximum feather fiber	Maximum damaged feathers	Maximum landfowl feathers	Maximum residue
95% down	95.0%	5.0%	5.0%	2.0%	2.0%	2.0%
90% down	90.0%	10.0%	10.0%	2.0%	2.0%	2.0%
85% down	85.0%	10.0%	10.0%	2.0%	2.0%	2.0%
80% down	80.0%	10.0%	10.0%	2.0%	2.0%	2.0%
75% down	75.0%	10.0%	10.0%	2.0%	2.0%	2.0%
70% down	70.0%	10.0%	10.0%	2.1%	2.0%	2.0%
65% down	65.0%	10.0%	10.0%	2.5%	2.0%	2.0%
60% down	60.0%	10.0%	10.0%	2.8%	2.0%	2.0%
55% down	55.0%	10.0%	10.0%	3.2%	2.3%	2.0%
50% down	50.0%	10.0%	10.0%	3.5%	2.5%	2.0%
40% down	40.0%	10.0%	10.0%	4.2%	3.0%	2.0%
30% down	30.0%	10.0%	10.0%	4.9%	3.5%	2.0%
20% down	20.0%	10.0%	10.0%	5.6%	4.0%	2.0%
10% down	10.0%	10.0%	10.0%	6.3%	4.5%	2.0%
5% down	5.0%	10.0%	10.0%	6.7%	4.8%	2.0%
Washed waterfowl feathers	--	10.0%	10.0%	7.0%	5.0%	2.0%

For additional information visit:

<http://standards.bsmi.gov.tw/>

IDFL LABORATORY AND INSTITUTE

Certified Laboratory: IDFB • EDFA • DPSC

Member: AATCC • ADFC • ASTM • CFDA • EDFA • IABFLO • IDFB

©2010

www.idfl.com

IDFL

Tel: +1 801 467 7611

email: info@idfl.com

IDFL EUROPE

Tel: +41 52 765 1574

email: europe@idfl.com

IDFL CHINA

Tel: +86 571 8273 6561

email: china@idfl.com